



## PRO SERIES



# FAST TRACK Rinse-Free Floor Stripper

Fast, powerful, rinse-free floor stripper provides premium performance and cuts through the heaviest layers of floor finish quickly on various flooring. Low pH formulation requires no neutralizing (flood) rinse and leaves no residue to effect floor finish application.

### Directions

- Dilute with warm water as follows:
  - Light Build-Up: 1:18 (7 oz. per gallon)
  - Regular Build-Up: 1:10 (12 oz. per gallon)
  - Heavy Build-Up: 1:8 (16 oz. per gallon)
  - Burnished Build-Up: 1:4 (32 oz. per gallon)
- Using a cotton mop, apply stripper solution liberally to all areas.
- Let stand for 5 - 10 minutes, making sure solution does not dry.
- Use a SSS PT2000 XHD Stripping Pad (or equivalent) and agitate all areas thoroughly with a low speed floor machine or auto scrubber.
- Use a wet vacuum or automatic scrubber to pick up all remaining solution from floor.
- Immediately rinse with clean water to remove residual soils, or squeegee marks.
- Let dry thoroughly and apply a recommended SSS Floor Finish from your Triple S distributor.

### Features

- Removes Multiple Layers of Finish from Burnished Floors
- No Neutralizing Rinse
- Ammonia Free
- Saves Time and Labor

### Recommended For

Removal of floor finish from burnished floor surfaces without the additional step of neutralizing.



### Specs

- Dilution:** 1:10-1:4
- pH Level:** 12.65-13.65
- Color:** Clear
- Fragrance:** Floral
- Pack:** 4/1 Gallon (#25139), 5 Gal Pail (#25140)

**Cuts Overall Stripping Time and Labor in Half**